




**DATE:** September 3, 2003

**TO:** King County International Airport Tenants  
distributed by e-mail and fax

**FROM:**   
Robert I. Burke, AAE, Airport Director

*for  
Reading  
file  
(Sent 9/3  
By RC)*

**SUBJECT: RWY 13R/31L Partial Closure -September 5, 2003 (Friday)**

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L on Friday, September 5. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Runway 13R/31L pavement maintenance work has been scheduled for **September 5, 2003 (Friday) from 09:00 - 14:00 (local time)**. The first **4000 feet of Runway 31L** will be **closed** and will have a **relocated threshold**. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REILs for Runway 31L will be out of service during this time.

Therefore, if 13R is active (south flow), there will be 6001 feet available for arrival and departure. If 31L is active (north flow), there will be 6001 feet available for departure and arrival.

**Please check NOTAMs daily for changes.**

\*\*\*\*\*  
\*\*\* MULTI TX/RX REPORT \*\*\*  
\*\*\*\*\*

TX/RX NO 0304

PGS. 1

TX/RX INCOMPLETE

TRANSACTION OK

[\*041]9p7677662

GALVIN-MAIT BLD  
RAINIER AVIATION

[\*048]9p7640142

[\*001]9p7677931

SEATTLEJETSVC

[\*002]9p7647102

AEROFLIGHT

[\*003]9p7621223

AIR TRANSPORT

[\*004]9p7630381

Airborne Express

[\*005]9p5211865

Airlift NW

[\*006]9p7626357

AIRPAC AIRLINES

[\*007]9p7632036

AMERICAN AVIONIC

[\*008]9p7636239

AMERIFLIGHT

[\*009]9p7621158

AVIATION PARTNER

[\*010]9p7633428

AVIATOR STORE

[\*011]9p7647112

AVIATION TRNG

[\*012]9p7620611

BAX GLOBAL

[\*013]9p6555116

BOEING CO

[\*014]9p7648124

CALIBER INSPECT

[\*015]9p7674018

CLASSIC HELICOPT

[\*016]9p7679333

GALVIN FLYING

[\*018]9p7689458

HELIJET

[\*019]9p7641904

KC JETCENTER

[\*020]9p7680483

KTC AVIATION

[\*021]9p7626046

LINDEAN AIRCRAFT

[\*022]9p7641312

NAT'L AVIATION

[\*023]9p7681715

NORDSTROM

[\*024]9p7634837

PISTOL CREEK

[\*025]9p7623542

SEA JET STREAM

[\*026]9p7633320

SERVICE GRP

[\*027]9p7630381

SOUND AERIAL SVY

[\*028]9p7641986

TAG AVIATION

[\*029]9p7674920

UPS

[\*030]9p5536851

US CUSTOMS

[\*031]9p5530190

US IMMIGRATIONS

[\*032]9p7643862

VALKERIE CORP

[\*033]9p7644760

WA AUDIOLOGY

[\*034]9p7671550

WA AIR NAT'L BRD

[\*035]9p7681947

NW SEAPLANES

[\*036]9p7674539

WESTERN METALS

[\*037]9p7679464

WINGSALOFT

[\*038]9p7645707

MUS OF FLIGHT

[\*039]9p7635156

S SEATTLE CC

[\*040]9p7622997

DUNCAN AVIONICS

[\*042]9p7633964

MENTE AVIATION

[\*043]9p7621561

EXEC FLIGHT

[\*044]9p7637761

OTTER CORP/JEM

[\*045]9p7625732

MJL AIRPARTNERS

[\*046]9p7674047

KGF AVIATION

[\*047]9p7625481

INTELL VENTURES

[\*049]9p7675604

AIRTECH

[\*050]9p7671726

CASCADE FLIGHT

[\*051]9p7094323

OLDTHYMEAVIATION


[\*052]54056

EMERGENCY MGMT

[\*053]60514

SAFETY &amp; CLAIMS

ERROR INFORMATION	[ 4]64271	SPEC_OPS/GUARD
	[*u55]8p6142381807p3947395	AIRNET
	[*056]8p6042734644p3947395	HELIJETFLITEOPS
	[*017]9p7689700	GUIDO PERLA



**DATE:** September 3, 2003

**TO:** King County International Airport Tenants  
distributed by e-mail and fax

**FROM:**   
Robert I. Burke, AAE, Airport Director

**SUBJECT: RWY 13R/31L Partial Closure -September 5, 2003 (Friday)**

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L on Friday, September 5. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Runway 13R/31L pavement maintenance work has been scheduled for **September 5, 2003 (Friday) from 09:00 - 14:00 (local time)**. The first **4000 feet of Runway 31L** will be closed and will have a relocated threshold. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REILs for Runway 31L will be out of service during this time.

Therefore, if 13R is active (south flow), there will be 6001 feet available for arrival and departure. If 31L is active (north flow), there will be 6001 feet available for departure and arrival.

**Please check NOTAMs daily for changes.**

\*\*\*\*\*  
\*\*\* TX REPORT \*\*\*  
\*\*\*\*\*

TRANSMISSION OK

TX/RX NO 0306  
RECIPIENT ADDRESS 97889700  
DESTINATION ID  
ST. TIME 09/04 08:21  
TIME USE 00:47  
PAGES SENT 1  
RESULT OK



**DATE:** September 3, 2003

**TO:** King County International Airport Tenants  
distributed by e-mail and fax

**FROM:**   
Robert I. Burke, AAE, Airport Director

**SUBJECT: RWY 13R/31L Partial Closure -September 5, 2003 (Friday)**

KCIA/Boeing Field will be performing routine pavement maintenance on Runway 13R/31L on Friday, September 5. This will be preventative maintenance primarily involving crack sealing and minor patching to ensure pavement integrity over its useful life.

Runway 13R/31L pavement maintenance work has been scheduled for **September 5, 2003 (Friday) from 09:00 - 14:00 (local time)**. The first **4000 feet of Runway 31L will be closed** and will have a **relocated threshold**. Additionally, taxiway intersections A10, A11, B7 and B10 will be closed. The PAPI and REELs for Runway 31L will be out of service during this time.

Therefore, if 13R is active (south flow), there will be 6001 feet available for arrival and departure. If 31L is active (north flow), there will be 6001 feet available for departure and arrival.